

Update from DUNE Laser Lab at LANL

DUNE-IoLS Meeting

Mattia + Laser crew (Eric, David, Sowjanya) - June 08, 2022

Test at 180 μs (from my last laser update)




- May 23
 - **QS = 180 μs**
 - No death
 - Energy measured (EM-1/2/3): 260/**38.1**/3
 - No plots. A software error stopped the acquisition
 - No big spike when opening the internal shutter but EM-2 energy much much lower than day 1: **38.1 mJ** Vs **72 mJ**.
 - Compatible with FHG windows damaged again
 - HG tuning was attempted after ~20 minutes data taking. 32 to 38 mJ
- Test will be repeated today

Repetition of Test at $QS = 180 \mu s$

- May 24
 - Needed to repeat test at $QS = 180 \mu s$
 - not recorded because of a bug in the acquisition code
 - The second test confirmed the decrease of energy: 38 mJ at full energy
 - Plots (Eric) are missing. All looked regular
- Strong indications the laser internal optics are damaged again

The usual movie


- FHG exit window looks damaged
- Unlike last time, FHG entrance window looks still okay
- Some dust inside the laser bench
- M2 collected 2 additional marks in the first two days of resumed activity
 - We realigned to a new spot after day 1 - still there since then
- No difference with the status of other optics (Attenuator, mirrors)



Recovering a workable energy level


+check for back reflections

- Two days, a dedicated setup. Highest 266-nm energy: 39 mJ, QS = 180 μ s
EM-1/2/3 = 1064/532/266 = 147/125/38
- Check for reflections
 - Checked everywhere with beam card
 - Measured around attenuator entrance (most reasonable source of reflections)
 - Reflection: 0.28 mJ
Other meters measuring compatible values
with the measurement at aligned HG, QS = 180 μ s: 142/125/0.28




Periscope material exposure to UV


Setup allows further tests on attenuator control



- Need to calibrate EM-1 (BS calibration data waiting for analysis)
- Components to test
 - Unmachined torlon plate
 - Unmachined PEEK plate
 - Machined torlon rod
 - Spare torlon holder for M4
 - Spare torlon target

Getting UV laser as close as possible to the edge





Alignment laser and
UV laser (pulsed)
aligned after M2

- Measurement plan (can be revised):
 - 1 hour warm up
 - 15 minutes exposure with energy equalized at 10 mJ
 - Close the shutter, check the status
 - 5+15 minutes exposure with energy equalized at 20 mJ
 - Close the shutter, check the status
 - 5+15 minutes exposure with energy equalized at 30 mJ
 - Close the shutter, check the status
 - 5 minutes + 3 hours exposure with energy equalized at 30 mJ
- Status
 - 15 minutes exposure at 18 mJ
 - No detectable effect on samples
 - Measurements paused because of a little bug
 - Eric realized a new attenuator calibration is needed
 - Measurements will be resumed this afternoon